

GRO

Mounting & Wiring

Installation Instructions

Knuckle or yoke mount · 120–277 VAC

A) MOUNTING METHODS

KNUCKLE MOUNT (STANDARD)

Fix the knuckle mount to the pole, arm or surface, set the aiming angle and lock the knuckle; the round canopy mounting plate (ordered separately) takes a ½" swivel arm on a standard 4" round junction box.

YOKE MOUNT OR GROUND STAKE (OPTIONAL)

Fit the yoke mount to a flat surface for the 4L and 7L sizes, or set the line-voltage ground stake where specified; keep the wireway gasket seated for the water-tight seal.

B) WIRING & SYSTEM TEST

1. Turn off the branch circuit before installation. All wiring per NEC and local code.
2. Connect the 120–277 VAC supply to the driver leads; connect the 0–10 VDC dimming leads to the control where dimming is used, observing polarity.
3. Energize and verify output and dimming.
4. Inspection: check the mounting hardware and the lens as local practice requires.

SAVE THESE INSTRUCTIONS

“Engineered for the spaces it protects.”